

# Lead in School Drinking Water Report

## Entiat Middle And High School



Date(s) collected: 2024-09-13

Date(s) analyzed: 2024-09-20

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
389679	Middle/High School	Sink - Multi-Compartment	Rm 109 Home And Family	4 of 5	Tap	center	59
389677	Middle/High School	Sink - Multi-Compartment	Rm 109 Home And Family	3 of 5	Tap	center	29
389693	Middle/High School	Sink	Rm 120	1 of 3 kitchen area	Tap	center	29
389673	Middle/High School	Sink - Multi-Compartment	Rm 109 Home And Family	1 of 5	Tap	center	28

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
389681	Middle/High School	Sink - Multi-Compartment	Rm 109 Home And Family	5 of 5	Tap	center	26
389688	Middle/High School	Sink	Rm 103	1 of 1	Tap	center	26
389685	Middle/High School	Sink	Rm 113	1 of 1	Tap	center	24
389683	Middle/High School	Sink	Rm 111	1 of 1	Tap	center	22
389663	Middle/High School	Sink	Rm 108	1 of 1	Tap	center	21
389692	Middle/High School	Sink	Rm 105	1 of 1	Tap	center	15
389675	Middle/High School	Sink - Multi-Compartment	Rm 109 Home And Family	2 of 5	Tap	center	4
389698	Middle/High School	Sink	Rm 107	1 of 1	Tap	center	3
389661	Middle/High School	Sink	Rm 107	1 of 1	Water Bottle Filler	right	2
389665	Middle/High School	Sink	Rm 108	1 of 1	Water Bottle Filler	right	2
389682	Middle/High School	Sink	Rm1 Music Rm	1 of 1	Tap	center	2

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
389690	Middle/High School	Sink	Rm 103	1 of 1	Water Bottle Filler	right	2
389691	Middle/High School	Sink	Rm 116 Used As Science Room Currently	2 of 2	Tap	center	2
389696	Middle/High School	Sink	Library Office 104	1 of 1	Tap	center	2
389687	Middle/High School	Sink	Rm 113	1 of 1	Water Bottle Filler	right	1
389689	Middle/High School	Sink	Rm 116 Currently Used As Science Room	1 of 2	Tap	center	1
389667	Middle/High School	Fountain - Multi-Level with Bottle Filler	Hs Boys Restroom	1 of 1	Water Fountain	left	<1
389669	Middle/High School	Fountain - Multi-Level with Bottle Filler	Hs Boys Restroom	1 of 1	Water Fountain	right	<1
389671	Middle/High School	Fountain - Multi-Level with Bottle Filler	Hs Boys Restroom	1 of 1	Water Bottle Filler	right	<1
389684	Middle/High School	Fountain with Bottle Filler	Middle School Restroom	1 of 1	Water Fountain	center	<1

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
389686	Middle/High School	Fountain with Bottle Filler	Middle School Bathroom	1 of 1	Water Bottle Filler	center	<1
389694	Middle/High School	Sink	Rm 105	1 of 1	Water Bottle Filler	right	<1
389695	Concessions/ Press Box	Sink	Kitchen	1 of 1	Tap	center	<1

**EXPLANATION OF TESTING AND RESULTS:**

Results in this report represent sampling conducted by Washington State Department of Health. Per **RCW 28A.210.410** sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: [leadfreekids@doh.wa.gov](mailto:leadfreekids@doh.wa.gov)